



Photo of deconstructed replacement board. Attempted mirror image of reverse (top) side for traces and mapping vias.



Comparison of replacement board to original (from original Japanese board?)



Mirror copy of original board to match new one  
Resistor values mirrored back for readability  
Opamps are now backwards (sorry)

